P-file Inspection
Floyd Country CC: OSCAY Barker
Don Daily



## **ENVIRONMENTAL MANAGEMENT CORPORATION** A BOC GROUP COMPANY

**MUNICIPAL SERVICES** www.emcinc.com

701 CHAMPION ROAD JEFFERSONVILLE. INDIANA 47130 TEL: (812) 285-6451 FAX: (812) 285-6454

March 29, 2004

Indiana Department of Environmental Management Mr. Oscar Barker Office of Water Quality 100 N. Senate Ave. P.O. Box 6015 Indianapolis, Indiana 46206-6015

Re: Highlander Point Shopping Center: IN 0050032 Violation Letter dated 3/8/04

Dear Mr. Barker:

On January 15, 2004 Mr. Barker preformed an inspection on the facility and commented that the mixed liquor was not settling very well at the time and the effluent was cloudy.

The cause of the upset condition was due to a build up of Nocardia in the process. At this time we have increased the waste rate to remove the Nocardia in the system. The owners have made the decision to have the grease interceptor pumped out on a monthly time schedule, instead of every two to three months. With the increased waste rate and the reduction of the grease source, we believe this should improve the facilities effluent.

Please contact me with any questions you may have on this matter.

Respectfully,

Timothy L. Crawford

EMC, Certified Operator

Cc: MEKA, Inc.